



Maricopa County

Air Quality Department

Compliance Division
1001 North Central Ave.,
Suite 125
Phoenix, Arizona 85004
Phone: 602-506-6010
Fax: 602-506-2163

Dear Responsible Party:

RE: Inspection Report - No Violation Noted

You are receiving this letter as a result of an inspection that was conducted at your site/facility. Enclosed with this letter is your Inspection Report to notify you of the results of your inspection.

The information located on the back page of this letter will clarify the acronyms and policies referenced in the Inspection Report. Further information about the Maricopa County Air Quality Department (MCAQD) Rules and Regulations can be found at the MCAQD website: www.maricopa.gov/aq

Additional information about how you can improve air quality in Maricopa County can be found at www.CleanAirMakeMore.com

If you have any questions, you may contact the inspector noted on your Inspection Report or contact a Maricopa County Air Quality Department Compliance Supervisor, at (602) 506-6734.

Thank you,

Air Quality Compliance Division
602-506-6734

Acronyms used in the Inspection Report:

\leq - Less than or equal to	CM - Certified Mail	NTV – Non Title V
\geq - Greater than or equal to	COMS - Continuous Opacity Monitoring System	O&M Plan – Operations and Maintenance Plan
AAP - Area Accessible to the Public	DCP – Dust Control Plan	PC – Permit Condition
ACWM – Asbestos Containing Waste Material	DGO – Dust Generating Operation	RACM – Regulated Asbestos Containing Material
ASHARA – Asbestos School Hazard Abatement Reauthorization Act	ECS – Emissions Control System	RM - Regular Mail
AHERA – Asbestos Hazard Emergency Response Act	HAP – Hazardous Air Pollutant	Stab. - Stabilize
ATI - At the time of inspection	HAPRACT – Hazardous Air Pollutant Reasonable Available Control Technology	TO - Track Out
AZMACT – Arizona Maximum Achievable Control Technology	HT - Haul Truck	TOCD – Track Out Control Device
CARB – California Air Resource Board	N/A - Not Applicable	VEE - Visible Emissions Evaluation
CEMS – Continuous Emission Monitoring System	N/O - Not Observed	VOC – Volatile Organic Compound

The owner/operator is ultimately responsible for maintaining the site/facility in compliance with Maricopa County rules and regulations at all times.

INSPECTION REPORT



Maricopa County Air Quality Department
1001 N. Central Avenue, Suite 125
Phoenix, AZ 85004
Phone: (602) 506-6010 Fax: (602) 506-2537
www.maricopa.gov/aq

Date: 01-Apr-14
Start Time: 0830 End Time: 0910
Inspector: Laurie Cline
Phone: 602.319.6003
Email: LauraCline@mail.maricopa.gov

Inspection Result:

No Violations Noted

Inspection Type: Detail inspection On-site

Inspection Purpose: Complaint

☒ Compliant CL

Complaint Number: 254834 & 254835

Permit/Notification Number:

040136

Hickman's Family Farms

6515 S Jackrabbit Tr

Buckeye

AZ 85326

Site Name: Hickman's Egg Ranch

Site Address:

32425 W Salome Hwy

City:

Arlington

Site Contact: Shari Yeatts

Phone:

623.692.8451

Inspection Rights Notification:

Read and Signed Rights

Comments

Notice of Inspection Rights read and signed by Shari Yeatts, Compliance Manager.

Inspection due to citizen complaints of odors received by Maricopa County Air Quality Department on 31Mar14. Refer to complaints 254834 and 254835.

Previous odor complaints:

06Mar14, Refer to complaint 254571

26Mar14, Refer to complaint 254788

No hydrogen sulfide odor was detected by inspector at time of inspection.

Per management, source will not be required to perform a compliance demonstration by conducting a test to monitor hydrogen sulfide levels at this time. This may be required in the future but source will be notified by Control Officer.

Discussed possible dust control issues on site of fertilizer plant with Fernando Ruiz.

☐ DOCUMENT REVISED

Delivery Method:

Date: 02-Apr-14

Regular Mail

OFFICE USE

rec:

rev: